
ORIG :	1 6 Oct 63 p 31	oved of Relea	sel <i>2</i> 002/07/30 /43	A-RDP75B0	028	5R0	003001800	064		a hang, a middelian ay of apportminist
UNIT :	CD/OSA 25X1A SECRET					2 MD/OSA			10	
DATE:	16 Oct. 1963		F-K-8275 T&P	Promitiga (s vincigas), salaman dilaga an appendia da sana adaph	3 4	D/	TECH FA	11		
ТО					5	-	/OGA	13		
10 :		25X1A			7	-)/08A 3/08A	14		
FROM	DIRECTOR				8	111	/ Our	15		
CONF	washio 2 VII		doel	· · · · · · · · · · · · · · · · · · ·	P E E C E		DEFERRED	F	RIORITY	MITIALS
INFO :	03A 1-	15	Cal		MOZMO	X	ROUTINE		ERATIONAL MEDIATE	INITIALS
										11
25X1A	25X1A							ĥi	T244:	16
то	25X1A	info				(CITE	fit	7244	16
то	CART	•	P 14 EA CYLINDE	rs, high p	RES				T244:	25X1
TO X	CART FIREWEL INST	RUCTED TO SHI	P 14 EA CYLINDE			SUR	E (5000 Þ	SI)	T244:	
∟ ox 25X1A ™ 0	CART FIREWEL INST	RUCTED TO SHIP RAGE. THESE (CYLINDERS HAVE	Besome sur	PLU	SUR S U	E (2000 P	SI)		

END OF MESSAGE

25X1A



o La De	2 03 23	Note of	* *	المنابة فأدغاؤه			
ROM	-			ROUTING	DATE		
UBJ.	Quit AT	ti reatment		HRC	23 oc		
		* 1 0 4 1	1.4	M			
					1		
					1		
		mo loca					
		- CONTRACT	3 6		-		
		- m)/cev					
					_		

25X1A

Approved For Release 2002/07/30: CIA-RDP75B00285R000300180006-4

OSA-5678-63

4 November

Dear Al:

Per our telecon it is decided that the neck seal in the full pressure suit is not desirable. All suits with the neck seal should be reconverted to the face seal and any present work to install the neck seal should be discontinued.

Request you modify suit by removing the 25X1A vent air ring at the wrists and boot tops. When the suit for 1045 is returned please modify it likewise. We will wait for comments from the pilots on this mod before changing any other suits.

Sincerely,

25X1A